



Overview: Part of spill impact on 12" Adibawa-Okordia pipeline at Ikarama. Picture was taken during Joint Investigation of 17th October, 2011.



Close-up: Spill due to Hacksaw cut on 12" Adibawa-Okordia pipeline at Ikarama. Picture was taken during Joint Investigation of 17th October, 2011.