



Overview: Part of spill impact on 18" Assa-Rumuekpe Pipeline route at Elele Alimini . Picture taken during Joint Investigation of 13-14th September, 2011



Close-up: Spill due to illegal fittings on 18" Assa-Rumuekpe Pipeline at Elele Alimini Picture taken during Joint Investigation of 13-14th September, 2011