



Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline route at Ikarama . Picture was taken during Joint Investigation of 9th September, 2011 .



Close-up: Spill due to Hack saw cut on 14" Okordia – Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 9th September, 2011