



Overview: Part of the spill impact on 6'' Obigbo North-Ogale pipeline right of way at Ogale  
Picture taken during Joint Investigation of 24<sup>th</sup> September,2011



Close-up: Spill point due to hacksaw cut on 6'' Obigbo North-Ogale pipeline at Ogale. Picture taken during Joint Investigation of 24<sup>th</sup> September,2011