



Overview: Part of spill impact on Jones Creek Wellhead 23SL at Kokodiagbene. Picture taken during Joint Investigation of 20th September, 2011



Close-up: Illegal fitting on Jones Creek Wellhead 23SL at Kokodiagbene. Picture taken during Joint Investigation of 20th September, 2011.