



Close up: Hacksaw cut on Ahia Well3S flowline at Omudioga. Picture was taken during Joint Investigation of 2<sup>nd</sup> May 2012.