



Overview: Part of spill impact on 18" Assa – Rumuekpe pipeline right of way at Awara. Picture was taken during Joint Investigation of 26<sup>th</sup> April 2012.



Close up: Illegal fitting on 18" Assa – Rumuekpe pipeline at Awara. Picture was taken during Joint Investigation of 26<sup>th</sup> April 2012.