



Overview: Part of spill impact on abandoned Oroni Well1 flowline right of way at Enhwe. Picture was taken during Joint Investigation of 2nd May 2012.



Close up: Cut section on abandoned Oroni Well1 flowline at Enhwe. Picture was taken during Joint Investigation of 2nd May 2012.