



Overview: Part of spill impact on 12" Imo River2 pipeline right of way at Owaza. Picture was taken during Joint Investigation of 24th April 2012.



Close up: Illegal fitting on 12" Imo River2 pipeline at Owaza. Picture was taken during Joint Investigation of 24th April 2012.