



**Overview:** Part of spill impact on 12" Imo River – Ogale pipeline at Owaza. Picture was taken during Joint Investigation of 17th April 2012.



**Close up:** Illegal fitting on 12" Imo River – Ogale pipeline at Owaza. Picture was taken during Joint Investigation of 17th April 2012.