Close up: Drilled hole on Imo River Well48L flowline at Igiriukwu. Picture was taken during Joint Investigation of 18th August 2012.