



Overview: Part of spill impact on 4 inch Otamiri Well 8L Flowline at Umuechem. Picture was taken during Joint Investigation of 15th Dec. 2012.



Close-up: Hacksaw cut on 4 inch Otamiri Well 8L Flowline at Umuechem. Picture was taken during Joint Investigation of 17th Dec. 2012.