



Overview: Part of spill impact on Nembe1 Well3S flowline right of way at Ewelesuo. Picture was taken during Joint Investigation of 28<sup>th</sup> December 2012.



Close up: Ruptured flowline on Nembe1 Well3S flowline at Ewelesuo. Picture was taken during Joint Investigation of 28<sup>th</sup> December 2012.