# THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0416 - 902081

Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

	ERAL INFORMATION:		nero by an the participating parties)
1. Spill i	incident Number: 9828	<b>≷</b> 1 2.Type o	of incident * GIL SPILL
3. Name	of Location OTAMIRI V	WELL 5 LIS FI	BNULWE
4. Name	of nearest community_Umu6c	tem_ 5. State: RIU	ECS 6. LGA ETCHE
7. Type	of Production facility/Installation	FLOWLING 8.A	sset owner/ District NELT P.H I
	DENT INFORMATION:		
a. b. c.	Date of incident:  Start date/time of investigation:  Investigation End date:  Description of spill point environr	ECEMBER, 2012	12
	Firmed soil	Loose soil	Previously excavated area
	☐Under water	Swampy	☐Exposed pipe surface
	Well Plateform (on Water) Description of leak point (tick as a	annlicable):	$\square_{ m Rig}$
e.	Drilled hole	Hack saw cut	☐Explosive tear,
	Complete Rupture	☐ Inward dent,	☐ Well head tampering
	Failed Weld-on illegal hot tap	valve,	☐ Missing Pipeline/Flowline)
	Crude oil theft (illegal) bunke		☐ Third party tampering with Clamp
	☐Third party tampering with va		☐Third party tampering with flange,
	Corrosion	☐Saver-pit over flow,	☐ Surge vessel overflow
	Outward dent	☐Flare System/Bund v	TOTAL PROPERTY OF THE PROPERTY AND THE PROPERTY OF THE PROPERT
	□Valve Failure	Com unit failure	Cold vent
	Relief valve failure	Others (specify)	
f.	Incident caused by:  Third party interference	☐ Operational	Mystery
g.	Spill point coordinates  Measuring unit	(minha	MID-BEIT)
	Northing:		Easting:
	114234	1.6	504459.2
		- W	

Page 1 of 9

### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 90208

Land	□ Swamp	□ Water	☐ Seasonal swamp
	of environment to		***
Land	□ Swamp	□ Water	□ River (identify)
□ Raining	er condition Sunny the nearest sensiti	ve habitat	
☐ Drinking v ☐ Built up ar ☐ Farmlands ☐ Fish Farm. ☐ Fishing ne ☐ Others (sp	ea /Pond t		KIL ,m
□ Others:			
. Any pictures o	r video coverage?		[Y] [N]
. Was there any	disruption to the	investigation?	[Y] [N]
give brief descrip	tion:		
N	OT	ADDI	100816
1 1	~ I	1111	A CINDLE

#### 15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NANE	ALTH	N	AOCA	XE IMPACT
	1 10111-1	/41110	1 +	INCA	01 11/11/01

### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0416 902081

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	CASSAVA		V	NIL	(34 × 40)m	
	-					

#### 17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
1	LONE WI	THIN ARE	AST	MOACT

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
N	ONE 1	LITHEN AREA	8F 1	MPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

ACTION O	F GTAMIRI WELL 5 45 FLOWLINE AT UMURCHAM.
	SHOWING HACKSAW CUT.
	60mm LENGHT of CUT AT
	3° CLOCK ASSITION AT OTAMIRI WALL 5 SIL FLOWLING
	AT Umaechem
Howline.	A
HOWLING.	- D FLOWLINE
	WALL HEAD  (OTAMIRI KIELL PAGE 3 OF 9
	5 4(5) Page 3 of 9

## JOINT INVESTIGATION REPORT FOR INCIDENT NO:

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing CMETERS	Easting METERS
	114234.23	504459.69
	114243.50	504 441. 15.
	114244.21	504441.66
	114242.94	504440.65
	114 23310	504462.19
	114232.25	504461.66
	114 253-25	504420.25
	14254.57	504421-18

#### G. INCIDENT INFORMATION:

(2017) (201	PARK TRANSPORT IN TAXABLE PARKET	Management of the Control of the Con	The second second second second
20	Impacted	Aran	Detaile
ZU.	HIHIDALLUU	nica	Details

	•	Total calculated area of impact	0.004449		
	•	Impact within SPDC R.O.W	YES		
	•	Impact outside R.O.W	No		======================================
21. <u>Y</u>	Volum	e of oil recovered before comp	oletion of JIV (VrecJ):		
		Reco	vered oil V <sub>rec</sub> r	NIL	1

20. Computation of the residual volume on site

a.		n of volume of pool of free phase oil (on land or con	fined water body). 2/ 2/
	i.	Area (m²) occupied by pool of free phase oil	26 M
	ii.	Average Depth (m) of pool of free phase oil	0.012m

#### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: iii. Emulsification factor: iv. Volume of pool of free phase oil. V pool: 90 barrels b. Computation of volume of infiltrated oil in the soil (Vint). 8m2 Area \*(m2) covered by the oil:\_ ii Area of the pool of free phase oil in touch with soil: NI-Average Depth (m) below ground surface of infiltration of oil: 0.015 m Soil type: CLAT $P_{\rm e}$ (effective porosity of the soil). Volume of infiltrated oil. Vinf barrels 21. Computation of volume of oil on open water based on standard coloration. Total area of oil on open water: NIL Table of average depth of oil on water based on coloration \*\* Thickness Percentage (mm) coverage Volume (m3) **Barely Visible** 0.00004 Silvery 0.00008 Slight Color 0.00015 Bright Color 0.0003 Dull 0.001 Dark 0.002 Black oil 0.1 Emulsion (30% Oil) MIL 100% **Total Volume** bbl iii. Volume of oil on open water. Vwat barrels NUL 22. Calculation of evaporated volume: Oil type: BOWHY MEDIUM E-Factor: 15 % ii. Volume of evaporated oil. V evap: iii. barrels

Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

<sup>\*</sup>If area is not same as the total area of impact, please indicate in the overview sketch \*\* Spill Factor from USCG FOG (2000 Edition)

#### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0410 - 902081

23. <u>Gros</u>	s Total Estimated S	pilled Volume				
V <sub>Est</sub> (bbls)	= $V_{evap}(bbls) + V_{wat}(bl)$	ols) + $V_{inf}$ (bbls) + $V_{pe}$	$_{\rm ool}$ (bbls) + $V_{\rm recJ}$ (bbl	ls)		
$V_{Est}(bbls) = =$	044+ MIL+	(0.50 + 0.66)	+1-90+1	11L =	2-90	BARRELS.
24. <u>Net</u>	Total Estimated Sp	illed Volume				
V <sub>Est</sub> (bbls	$= V_{evap}(bbls) + 0.6*V$	$_{\text{wat}}$ (bbls) + $V_{\text{inf}}$ (bbls)	+ V pool (bbls) + V re-	c) (bbls)		
VEst(bbls)=	3 BARRELS.					

#### 25. GENERAL STATUS OF THE SITE

- A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out □
- B. Investigation of the incident site showed that there is residual impact on site requiring further works

#### **26 REPRESENTATIVES**

This report was filled and signed on the investigation representatives from

- Host Community
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]: ☑
- Nigeria Police Force [NPF]:□
- Shell Petroleum Development Company [SPDC]:

Tick as applicable

<sup>\*</sup>Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site

<sup>\*</sup>Conversion of m3 to barrels is Total volume VT (m3) x 6.29

<sup>\*</sup>Emulsification factor for spill on water to consider is 60% of volume of oil.

#### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITÉD

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0416-90208

27. Appendix 1: Overview sketch of the site

Location:	OTAMIRI WELL SSIL FLOWLINE AT UMBEHEN	7.
	TOTAL FISCHUMED LENGHT CONTRACT CONTRAC	7
	Ason I	/
	Strong strong of the strong of	
	Strate of John William	
Been	Design And Market Marke	
4	W. C. L.	