



Overview: Part of spill impact on 12" Oguta-Egbema pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 19th February 2012.



Overview: Part of spill impact on 12" Oguta-Egbema pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 19th February 2012.



Overview: Part of spill impact on 12" Oguta-Egbema pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 19th February 2012.



Close-up: Drilled hole on 12" Oguta-Egbema pipeline at Obiakpu. Picture was taken during Joint Investigation of 19th February 2012.