



Overview: Part of spill impact on 12" Adibawa-Okordia pipeline right of way at Edagberi-Betterland. Picture was taken during Joint Investigation of 9<sup>th</sup> March 2012.



Close up: Tear at 6 o'clock position on 12" Adibawa-Okordia pipeline at Edagberi-Betterland. Picture was taken during Joint Investigation of 9<sup>th</sup> March 2012.