



Overview: Part of spill impact on 6" Obigbo North – Ogale pipeline right of way at Ogale. Picture was taken during Joint Investigation of 15th February 2012.



Close-up: Hacksaw cut on 6" Obigbo North – Ogale pipeline at Ogale. Picture was taken during Joint Investigation of 15th February 2012.