



Overview: Part of spill impact on 36" Npoku-Bomu trunkline right of way at Agbonchia. Picture was taken during Joint Investigation of 23<sup>rd</sup> February 2012.



Close up: Drilled holes on 36" Npoku-Bomu trunkline at Agbonchia. Picture was taken during Joint Investigation of 23<sup>rd</sup> February 2012.