



Overview: Part of spill impact on on 18" Assa-Rumuekpe pipeline right of way at Awara. Picture was taken during Joint Investigation of 24th February 2012.



Close-up: Failed clamps on 18" Assa-Rumuekpe pipeline at Awara. Picture was taken during Joint Investigation of 25th February 2012.