



Overview: Part of spill impact on 6" Obigbo North pipeline at Ogale. Picture was taken during Joint Investigation of 3<sup>rd</sup> February 2012.



Close-up: Illegal fittings on 6" Obigbo North pipeline at Ogale. Picture was taken during Joint Investigation of 3<sup>rd</sup> February 2012.