



Close-up: Illegal fittings on 28" Npoku-Bomu pipeline at B-Dere. Picture was taken during Joint Investigation of 14th February 2012.