



Overview: Part of spill impact on 12" Imo River2 pipeline right of way at Owaza. Picture was taken during Joint Investigation of 15<sup>th</sup> February 2012.



Close-up: Illegal fittings on 12" Imo River2 pipeline at Owaza. Picture was taken during Joint Investigation of 15<sup>th</sup> February 2012.