



Overview: Part of spill impact on Kanbo Well5 flowline right of way at Egbema-Angalabiri. Picture was taken during Joint Investigation of 24th February 2012.



Close up: Spill point on Kanbo Well5 flowline at Egbema-Angalabiri. Picture was taken during Joint Investigation of 1st March 2012.