



Overview: Part of spill impact on 28" Npoku-Bomu pipeline right of way at B-Dere. Picture was taken during Joint Investigation of 11th February 2012.



Close-up: Illegal fittings on 28" Npoku-Bomu pipeline at B-Dere. Picture was taken during Joint Investigation of 11th February 2012.