



Overview: Oil sheen from SPM3 Bonny Crude Loading Platform. Picture was taken during Joint Investigation of 27th February 2012.



Close-up: Failed hose from SPM3 Bonny Crude Loading Platform. Picture was taken during lifting of string from sea bed on 27th February 2012.