



Overview: Part of spill impact on 36" Nkpoku-Bomu pipeline right of way at Atali. Picture was taken during Joint Investigation of 28th July 2012.



Close up: Illegal fittings on 36" Nkpoku-Bomu pipeline at Atali. Picture was taken during Joint Investigation of 29th July 2012.