



Overview: Part of spill impact on 28" Nkpoku-Bomu pipeline right of way at Gio. Picture was taken during Joint Investigation of 12<sup>th</sup> July 2012.



Close up: Illegal fitting on 28" Nkpoku-Bomu pipeline at Gio. Picture was taken during Joint Investigation of 12<sup>th</sup> July 2012.