



Overview: Part of spill impact on 8" Umuechem-Nkpoku delivery line right of way at Umuechem. Picture was taken during Joint Investigation of 21st July 2012.



Close up: Illegal fitting on 8" Umuechem-Nkpoku delivery line at Umuechem. Picture was taken during Joint Investigation of 21st July 2012.