



Overview: Part of spill impact on 36" Rumuekpe-Nkpoku Trans Niger Pipeline right of way at Mgbodo-Aluu.



Close up: Illegal fitting on 36" Rumuekpe-Nkpoku Trans Niger Pipeline at Mgbodo-Aluu. Picture was taken during Joint Investigation of 9th July 2012.