

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

(Note: 710 produced do produced mile environmental mental mile environmental mental me					
A. GENERAL INFORMATION:					
1. Spill incident Number: 84311		fincident* OIL SPILL			
3. Name of Location 12" MOR	IVERITE OGA	IF PIPELINE			
4. Name of nearest community OWA					
7. Type of Production facility/Installation	IL PIPELINES. A	sset owner/ District NPF / PH 2			
B. INCIDENT INFORMATION:					
9. Details of incident a. Date of incident: b. Start date/time of investigation: c. Investigation End date: d. Description of spill point environm Firmed soil		Previously excavated area			
	Loose soil	<u> </u>			
Under water	□ Swampy	Exposed pipe surface			
Well Plateform (on Water)e. Description of leak point (tick as a)	nnlicable):	\square_{Rig}			
_	_	☐Explosive tear,			
□Drilled hole	∐Hack saw cut	<u> </u>			
☐Complete Rupture	∐Inward dent,	Well head tampering			
Failed Weld-on illegal hot tap v		☐ Missing Pipeline/Flowline)			
Crude oil theft (illegal) bunkeri		☐ Third party tampering with Clamp			
☐Third party tampering with val	_	☐ Third party tampering with flange,			
☐Corrosion	☐Saver-pit over flow,	☐ Surge vessel overflow			
Outward dent	☐ Flare System/Bund w	all failure			
□Valve Failure	Com unit failure	☐ Cold vent			
Relief valve failure	Others (specify)				
f. Incident caused by:					
Third party interference	☐ Operational	□Mystery			
g. Spill point coordinates Measuring unit METERS	M10-B2	ELT) MINNA			
Northing:	[]	Easting:			
103314	29	524761 15			
No.					
	<u>_</u> <u> </u>				

Page 1 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0384 843118

C.	RISK ASSESSMEN	IT.			-
	10. Type o	of environment:			
	Land	□ Swamp	□ Water	☐ Seasonal swamp	
	i. Type of	environment to	which oil has sp	read:	
	🔏 Land ,	□ Swamp	□ Water	☐ River (identify)	
	ii. Weathe	r condition			
	Raining 11. Distance from th	□Sunny se nearest sensiti	ve habitat	•	
	Government Drinking wa Built up area Farmlands Fish Farm/P Fishing net Others (spec	ater source a ond cify). PALM Ta	RE PLANTA	[m,m] [m,] [m,] [m,] [m,]	
	□ Booms	☐ Trench	□ Dyke		
	Others:	NONE			
	13. Any pictures or	video coverage?		[N] [N]	
	14. Was there any di	isruption to the i	nvestigation?	[Y] [N J	
If y	es give brief description	on:	λ		
_	MA		APPI	ICARIE	
	1401		/ /	-ICAPLL	

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
		ļ			
 1		 -	4		
HV	17		 Λ		1
	11)KIE V/	1 11 161	 	<u> </u>	E MPACT
		1 1 1 1 1 1 1	1 11		HITTC I
	·				

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 8413118

16. Crops/Economic Trees

S/N Type of crops	Young	Medium	Matured	Quantity	Comments
NONE	WITHIN	· ARE	A OF	MPAC	T

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
*	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			~
 \ 	HNF WI	HIN AREA	() - IV	PAC
• • • • • • • • • • • • • • • • • • •	- 1 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			<u> </u>

18. Others (Specify) i.e. Animal Traps

S/N Others	Description		Quantity/Size	Comments
NONE	MTHIN	ARE/	A OF	MPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1) CONNECTING SECTION I" PIPE 12" IMO RIVER OGALE PIPELINE AT DWAZA SHOWING POSITION CRUBE OIL THEFT FITTING. BALL VALVES PIPE DRILL AT ILLEGAL FITTING IMO RIVER I Page 3 of 9

OGALE

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1384 843118

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

(MD-DELI) MA

		<u> </u>
S/N	Northing METERS	Easting Verens
1	103313.12	524763-08
2	103313.15	524750.76
3	103316.21	524753.85
4	103316.19	524763.09
_		
<u>-</u>		
G. INCL	DENT INFÓRMATION:	
20.	Impacted Area Details	
	Total calculated area of impact	0.003Ha
	Impact within SPDC R.O.W	
	Impact outside R.O.W	
21. 3	Volume of oil recovered before completion of	IIV (V _{rec} j):

Recovered oil V_{rec}r

a. Computation of volume of pool of free phase oil (on land or confined water body).

i. Area (m²) occupied by pool of free phase oil.

ii. Average Depth (m) of pool of free phase oil _

20. Computation of the residual volume on site

Nli

0.04

barrels

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: iii. Emulsification factor: iv. Volume of pool of free phase oil, V pool barrels Computation of volume of infiltrated oil in the soil (V_{inf}). Area *(m2) covered by the oil:_ Area of the pool of free phase oil in touch with soil: NII ii Average Depth (m) below ground surface of infiltration of oil:_ iii P_c (effective porosity of the soil). \mathbf{v} Volume of infiltrated oil. Vinf barrels 21. Computation of volume of oil on open water based on standard coloration. Total area of oil on open water: í. 11. Table of average depth of oil on water based on coloration ** Thickness Percentage (mm) coverage Volume (m3) Barely Visible 0.00004 Silvery 0.00008 Slight Color 0.00015 Bright Color 0.0003 Dull 0.001 Dark 0.002 Blackoil 0.1 Emulsion (30% Oil) 100% NIL bbl Percent Total **Total Volume** Volume of oil on open water. Ve iii. barrels NII 22. Calculation of evaporated volume: Oil type: RONNY MEDIUM ii. E-Factor: iii. Volume of evaporated oil: V evap: barrels 0.15

Evaporation Factors (E-Factor) for SPDC Crude oil			
Oil Type Days on site Bonny Light Bonny			
			Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%


^{*}If area is not same as the total area of impact, please indicate in the overview sketch ** Spill Factor from USCG FOG (2000 Edition)

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0384 843118
23. <u>Gross Total Estimated Spilled Volume</u> 0-15 + N/L + 0-58 + 0-25 + N/L = 0-98
$V_{\text{Est}}(\text{bbls}) = V_{\text{evap}}(\text{bbls}) + V_{\text{wat}}(\text{bbls}) + V_{\text{inf}}(\text{bbls}) + V_{\text{peol}}(\text{bbls}) + V_{\text{recJ}}(\text{bbls})$
VEA (bbls)= BARREL
24. Net Total Estimated Spilled Volume 0.15+ NIL+ 0.58
$V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls)$
VEst(bbis)= BARREL
*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29
*Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact after the
initial response and therefore recommend that the site be closed out
B. Investigation of the incident site showed that there is residual impact on site requiring
further works 🔽
26 REPRESENTATIVES
This report was filled and signed on the 12/07/2012 at incident site by joint
investigation representatives from
Host Community
• Department of Petroleum Resources [DPR]: □✓
• National Oil Spill Detection and Response Agency [NOSDRA]:
State Ministry of Environment [SME]:
Nigeria Police Force [NPF]:
Shell Petroleum Development Company [SPDC]:

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0384843118

27. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0324 843118

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	-	
	<u> </u>	<u> </u>
<u></u>		<i>f</i>
-		
	 	
	 	
		
/	'	