



Close up: Illegal fitting on 12" Imo River2 – Ogale pipeline at Owaza. Picture was taken during Joint Investigation of 18th July 2012.



Close up: Illegal fittings on 12" Imo River2 – Ogale pipeline at Owaza. Picture was taken during Joint Investigation of 19th July 2012.