JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0312 839838

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:		
1. Spill incident Number: 8398	2.Typ	e of incident * OIL SPILL
3. Name of Location 12" KOKO	RI-ERIEMU P	PELINE @ DRPARA (AGBARHA-
4. Name of nearest community <u>OMA</u> \	10VWE 5. State:	DELTA 6. LGA UGELLI MORTH
7. Type of Production facility/Installation	PIPELINE 8	. Asset owner/ District PIPELINE
B. INCIDENT INFORMATION:		
a. Date of incident: b. Start date/time of investigation: c. Investigation End date: d. Description of spill point environ Firmed soil Under water Well Plateform (on Water) e. Description of leak point (tick as Drilled hole Complete Rupture Failed Weld-on illegal hot ta Crude oil theft (illegal) bunk Third party tampering with v Corrosion Outward dent Valve Failure Relief valve failure	nment  Loose soil  wampy  s applicable);  Hack saw cut  Inward dent, p valve, ering) point,	
f. Incident caused by:  Third party interference	☐ Operational	□Mystery
g. Spill point coordinates  Measuring unit		
Northing:		Easting:
1727	17	403484

Page 1 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0312 839838

	MENT		
10. Ty	pe of environment:		
Land	□ Swamp	□ Water	Seasonal swamp
i. Tyŗ	e of environment to	which oil has sp	oread:
Land	⊠Śwamp	Water	□ River (identify)
ii. We	ather condition		
☐ Raining  Distance fro	Sunny m the nearest sensiti	ve habitat	
☐ Drinkin☐ Built up☐ Farmlar☐ Fish Farmlar☐ Chers (☐ Dring ☐ Dring ☐ Dring ☐ Dring ☐ Drinking ☐ Dr	ds m/Pond	PEN)	ted area [ ,m] [ ,m] [ ,m] [ 0 ,m] [ 5 ,m] [ ,m]
□ Booms	☐ Trench	□ Dyke	
☐ Others:	_ <del></del>		<del></del>
3. Any pictures	or video coverage?		[W] [N]
4. Was there a	ny disruption to the	investigation?	[Y] [W]
give brief desc	ription:		
	XIDT	APPI	ICABLE

# 15. Structures / Properties

S/N	Type of Structures	Description	Size	Number		Comments
					NS-	IMPACT
		100	1414	AKETT		
<u> </u>	MONE	VVI				
	<u> </u>	<u> </u>	<del> </del>			

JOINT INVESTIGATION REPORT FOR INCIDENT NO:\_\_\_\_

**0312** 839838

### 16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
01	PALW				LOT	IMPACTED
0)	RUBBER				LOT	IMPACTED


#### 17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<u> </u>		<del></del>		NUPACT
<del></del>	LIDNE	WITHIN	AREA ST	(MPAC)
	/\/\/\			

#### 18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
		MITHIA	ARIEA OF	IMPAC'I
	MOME			

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)



# THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0312 839838

#### F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
	172715	403485
	172716	403485
	172717	403 481
·—— <u>—</u>	172713	403481
	172713	403482
	172715	403483
	172728	403486
	172729	403490
	172712	403490
·	172684	403488
	172611	403485
	172610	403480
	172580	403482

#### G. INCIDENT INFÓRMATION:

20	Impacted	1 Area	Details

21.	Total calculated area of impact  Impact within SPDC R.O.W  Impact outside R.O.W  Volume of oil recovered before completion of JIV (V <sub>recJ</sub> ):  Total calculated area of impact  20576 M <sup>2</sup> 1394 M <sup>2</sup> 19182 M <sup>2</sup> Volume of oil recovered before completion of JIV (V <sub>recJ</sub> ):	
	Recovered oil Viet 15	barrels
20.	Computation of the residual volume on site	•
a.	i. Area (m²) occupied by pool of free phase oil	
1 :	ii. Average Depth (m) of pool of free phase oil	<u> </u>

	•	PORT FOR INCIL		0312	_8398:	38
iii. Emulsification		50%				
iv.	Volume of	pool of free phase	oil.V <sub>pool</sub>	144.2	2	barrels
b. Computation	of volume of infile	trated oil in the soi	1 (V <sub>inf</sub> ).			
i	Area *(m²) co	overed by the oil:_	145	8 m	·	
i		ool of free phase o		_	<del>ر</del>	
· i				infiltration of oil:		m_
i		SAND (ME	~			_
3		porosity of the soi	•	25 %		
i	v. Volume	of infiltrated oil.	V	115.	33	barrels
21. Computation i. Total area of	of oil on open wate	er: <u> </u>	111-	ndard coloration.	٠.	
ii. Table of ave	erage depth of oil o	on water based on co	loration **			
	Thickness (mm)	Percenta coverag		Volume (m	3)	
Barely Visible	0.00004					
Silvery	0.00008					
Slight Color				CABLE		·
Bright Color		<del> </del>	1 V			
Dull	0.001	<del>                                     </del>	PPL	<del>· ·</del>		
Dark	0.002	1	· `			•
Blackoil Emulsion (30% Oil)	0.1	10,		<del></del>	<del></del>	
Emulsion (30 % On)	Percent Total		100%	Total Volume		ы
· iii.		il on open water.				barrels
22. Calculation o				<u>-</u>	<del></del>	
	-				•	
i. Oil t	ype: Bomn	A WEDIAM				
ii. E-Fa	actor: 15 %	6_				
iii.	Volume of e	vaporated oil. V eve		48.45		barrels
Evanora	tion Factors (F-Fac	tor) for SPDC Crud	e oil			
Oil Type	Days on site	Bonny Light	Bonny Medium			
Period Since Oil Spill	< 1 day	10%	5%	-		
	1-7 days	25%	15%		*	
	> 7 days	40%	25%	1		

Page 5 of 9

<sup>\*</sup>If area is not same as the total area of impact, please indicate in the overview sketch \*\* Spill Factor from USCG FOG (2000 Edition)

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0312 8398 38

23. Gross Total Estimated Spilled Volume	
$V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$	
VEST (bbls) = 323 BBLS	
24. Net Total Estimated Spilled Volume	
$V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$	
VEst(bbls)= 323 BBLs	

#### 25. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact—after the initial response and therefore recommend that the site be closed out □
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

#### **26 REPRESENTATIVES**

This report was filled and signed on the 13/07/2012 at incident site by joint investigation representatives from

- Host Community ☑
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]: ☑
- Nigeria Police Force [NPF]:☑
- Shell Petroleum Development Company [SPDC]: ☑

Tick as applicable


<sup>\*</sup>Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site

<sup>\*</sup>Conversion of m3 to barrels is Total volume VT (m3) x 6.29

<sup>\*</sup>Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0312 839838

## 27. Appendix 1: Overview sketch of the site



# 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	172581	403479
	172509	403480
	172 485	403459
	172517	403429
	172537	403419
<u></u>	172 410	403454
	172335	403 433
	172674	403481
	172 674	403477
	172714	403479
	172450	403339
	172450	403339
	172444	403460
	172514	403470
	172479	403473
	172522	403365
	172337	403395
Ĺ	172359	403363