



Overview: Part of spill impact on 16" Uzere-Eriemu trunkline right of way at Iyede. Picture was taken during Joint Investigation of 5th July 2012.



Close up: Illegal fitting on 16" Uzere-Eriemu trunkline at Iyede. Picture was taken during Joint Investigation of 5th July 2012.