



Overview: Part of spill impact on 12" Kokori-Eriemu pipeline right of way at Omavovwe. Picture was taken during Joint Investigation of 12th July 2012.



Overview: Part of spill site impacted by bush fire on 12" Kokori-Eriemu pipeline right of way at Omavovwe. Picture was taken during Joint Investigation of 13th July 2012.



Close up: Illegal fittings on 12" Kokori-Eriemu pipeline at Omavovwe. Picture was taken during Joint Investigation of 12th July 2012.