



Overview: Part of spill impact on Cawthorne Channel 2 Well51T flowline right of way at Mbiama. Picture was taken during Joint Investigation of 18th July 2012.



Closeup: Pinhole on Cawthorne Channel 2 Well51T flowline at Mbiama. Picture was taken during Joint Investigation of 18th July 2012.