




Overview: Site of spill on Awoba Well8T Flowline Right of Way at Bille. Picture was taken during Joint Investigation of 31st October 2014.



Close-up: Tear on Awoba Well8T Flowline at Bille. Picture was taken during Joint Investigation of 31st October 2014.