



Overview: Part of spill impact on 28" Nkpoku-Bomu pipeline right of way at Gio.
Picture was taken during Joint Investigation of 26th June 2012.



Overview: Burnt illegal refinery near the impacted area on 28" Nkpoku-Bomu pipeline right of way at Gio.



Close up: Illegal fitting on 28" Nkpoku-Bomu pipeline at Gio. Picture was taken during Joint Investigation of 26th June 2012.



Close up: Illegal fitting on 28" Nkpoku-Bomu pipeline at Gio. Picture was taken during Joint Investigation of 26th June 2012.