



Close up: Pinhole leak on 24" Alakiri-Bonny pipeline at Fusokiri/Ilomaturu located through injection of pressure on the line on 2nd August 2012. Picture was taken during Joint Investigation of 5th August 2012.