



Overview: Part of spill impact on 24" Alakiri – Bonny Pipeline route at Kalibiama. Picture was taken during Joint Investigation of 17<sup>th</sup> July 2012.



Close-up: Drilled holes on 24" Alakiri – Bonny Pipeline at Kalibiama. Picture was taken during Joint Investigation of 19<sup>th</sup> August 2012.



Close-up: External grind off surface on 24" Alakiri – Bonny Pipeline at Kalibama.  
Picture was taken during Joint Investigation of 19<sup>th</sup> August 2012