



Overview: Part of spill impact on 18" Assa-Rumuekpe pipeline right of way at Omudioga. Picture was taken during Joint Investigation of 7th June 2012.



Close up: Illegal fitting on 18" Assa-Rumuekpe pipeline at Omudioga. Picture was taken during Joint Investigation of 7th June 2012.