



Overview: Part of spill impact on 20" Rumuekpe-Nkpoku trunkline right of way at Ibaa. Picture was taken during Joint Investigation of 16<sup>th</sup> June 2012.



Close up: Drilled hole on 20" Rumuekpe-Nkpoku trunkline at Ibaa. Picture was taken during Joint Investigation of 16<sup>th</sup> June 2012.