



Overview: Part of spill impact on 24" Npoku-Bomu pipeline right of way at Ogale. Picture was taken during Joint Investigation of 15<sup>th</sup> June 2012.



Close up: Spill point due to corrosion on 24" Npoku-Bomu pipeline at Ogale. Picture was taken during Joint Investigation of 15<sup>th</sup> June 2012.