



Overview: Part of spill impact on 10" Diebu Creek pipeline right of way at Onyoma. Picture was taken during Joint Investigation of 23rd June 2012.



Close up: Hacksaw cut on 10" Diebu Creek pipeline at Onyoma. Picture was taken during Joint Investigation of 23rd June 2012.