



Overview: Part of spill impact on 24" Npoku-Bomu pipeline right of way at Bera.
Picture was taken during Joint Investigation of 9th June 2012.



Close up: Hacksaw cut on 24" Npoku-Bomu pipeline at Bera. Picture was taken during
Joint Investigation of 9th June 2012.