



Overview: Part of spill impact on 24" Nembe Creek pipeline right of way at Segoo. Picture was taken during Joint Investigation of 10th June 2012.



Close up: Illegal fittings on 24" Nembe Creek pipeline at Segoo. Picture was taken during Joint Investigation of 10th June 2012.



Close up: Illegal fitting on 24" Nembe Creek pipeline at Segoo. Picture was taken during Joint Investigation of 10th June 2012.