



Overview: Part of spill impact on 8" Nkali pipeline right of way at Odagwa. Picture was taken during Joint Investigation of 15th March, 2012.



Close-up: Illegal fitting on 8" Nkali pipeline at Odagwa. Picture was taken during Joint Investigation of 15th March, 2012.