



Overview: Part of spill impact on 12" Kokori-Eriemu delivery line right of way at Oteri. Picture was taken during Joint Investigation of 22nd March 2012.



Close up: Inward dent and tear on 12" Kokori-Eriemu delivery line at Oteri. Picture taken during repair of delivery line on 25th March 2012.