



Overview: Part of spill impact on 36" Rumuekpe-Nkpoku pipeline right of way at Omuigwe-Aluu. Picture was taken during Joint Investigation of 2<sup>nd</sup> March 2011.



Close up: Illegal fitting on 36" Rumuekpe-Nkpoku pipeline at Omuigwe-Aluu. Picture was taken during Joint Investigation of 2<sup>nd</sup> March 2011.