



Overview: Part of spill impact on 10" Diebu Creek – Nun River pipeline right of way at Oporoma. Picture was taken during Joint Investigation of 17<sup>th</sup> April 2012.



Close up: Inward dent on 10" Diebu Creek – Nun River pipeline at Oporoma. Picture was taken during Joint Investigation of 17<sup>th</sup> April 2012.