



Overview: Part of spill impact 10" Ekulama1-Sanbarth pipeline right of way at Ekulama1. Picture was taken during Joint Investigation of 19th May 2012.



Close up: Illegal fitting on 10" Ekulama1-Sanbarth pipeline at Ekulama1. Picture was taken during Joint Investigation of 20th May 2012.